



## WARNING



**INSTALLATION OF THIS AIR SPRING ONTO A DEFECTIVE SHOCK CAN CAUSE DAMAGE AND/OR VOID WARRANTY.**

**CAUSE: BLOWN SHOCKS**

- EXCESSIVE OIL LEAKING FROM TOP OF SHOCK TUBE
- LITTLE OR NO PRESSURE/RESISTANCE FROM SHOCK



**IF EVIDENCE OF A BLOWN SHOCK IS FOUND,  
PLEASE REFER TO ARNOTT PART #'S:  
REMANUFACTURED: AS-2450, AS-2451, AS-2394 & AS-2463  
NEW: AS-2792, AS-2789 & AS-2802  
FOR COMPLETE AIR STRUT REPLACEMENTS.**

**Arnott® is committed to the quality of its products. If you have a question or problem with any Arnott product, please contact Arnott by calling 800-251-8993 during normal business hours or email [techassistance@arnottinc.com](mailto:techassistance@arnottinc.com). (In the EU please call +31 (0)73 7850 580 or email [info@arnotteurope.com](mailto:info@arnotteurope.com))**