



LuK Service Info



Clutch actuation force too high

Incorrect assignment of the clutch results in a malfunction

Manufacturer: Mercedes Benz

Model: Atego I

Part no.: 640 3014 09
640 3111 09

See parts catalog for current assignment




Figure 1: Clutch set 640 3014 09 (for vehicles with a clutch booster)

There are two versions of the clutch actuator on the manual gearboxes of the vehicle model specified above. There are versions with and without a clutch booster. For models with a clutch booster, clutch kit 640 3014 09 must be used. For models without a clutch booster, clutch kit 640 3111 09 must be used.

Clutch kit 640 3014 09 (for models with a clutch booster) must not be installed in a vehicle without a clutch booster. In this case, the clutch cannot be actuated or will be very difficult to actuate and the vehicle cannot be driven.

To avoid incorrect assignment, information (for vehicles with/without a clutch booster) is included for the relevant clutch sets in the catalog. These make clear identification possible.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk

SCHAEFFLER
REPXPERT